



A/C Bypass Pulleys

Run your vehicle without the A/C Compressor

BEFORE



AFTER



PROBLEM

- Torn serpentine belt
- Seized A/C compressor renders car inoperable
- 10-year, 100,000 mile vehicle estimated worth \$1,000 - \$2,000

OPTIONS

- Customer can't afford a complete repair
- Replace A/C Compressor –
Estimated List & Labor: \$1,000

SOLUTION

- Remove A/C compressor
- Install new A/C Bypass Pulley
- Install new belt and pulley
- ***Estimated List & Labor: \$150***

63 SKUs covering over 64 million vehicles



Covering Over
3 Million Vehicles!

34174
GM 2003-96,
Isuzu 1998-97




Covering Over
5 Million Vehicles!

34184
Ford, Mazda
2003-86



Covering Over
3 Million Vehicles!

34166
Ford 3.0, 4.6L
2003-92



Covering Over
2 Million Vehicles!

34152
GM 4.3, 5.0, 5.7L
1995-87



Covering Over
2 Million Vehicles!

34241
Grand Caravan,
Town & Country
2007-01

See Back for
Applications...

A/C Bypass Pulleys

Dorman's Top Applications

Make	Model	Year	Dorman #
Dodge	Dakota	2001-94	34178
Dodge	Dakota 2.5L	2002-96	34237
Dodge	Dakota, Durango 4.7L	2001-00	34238
Dodge	Durango	2001-88	34178
Dodge	Ram 1500/2500/3500 Pick-ups	2002-94	34178
Dodge	Voyager, Grand Voyager, Town & Country, Caravan, Grand Caravan	2000-96	34156
Dodge	Voyager, Grand Voyager, Town & Country, Caravan, Grand Caravan 3.3/3.8L	2007-01	34241
Ford	Aerostar 3.0/4.0L	1997-90	34182
Ford	Continental	2002-95	34166
Ford	Crown Victoria, Grand Marquis	2002-93	34191
Ford	E/F-Series, Bronco	1996-90	34150
Ford	Escort 1.9/2.0L	2002-92	34182
Ford	Explorer 5.0L	2001-96	34182
Ford	F-250/350/Super Duty	1997	34150
Ford	F-Series Pick-ups 4.6/5.4/6.8L	2001-97	34188
Ford	Mark VIII	1998-93	34191
Ford	Mountaineer 5.0L	2000-97	34182
Ford	Mustang	2003-96	34191
Ford	Ranger 2.3L	1997-90	34150
Ford	Taurus, Sable	2003-92	34166
Ford	Thunderbird 5.0L	1993-91	34182
Ford	Thunderbird, Cougar 4.6L	1997-94	34191
Ford	Tracer 1.9/2.0L	1999-92	34182
Ford	Windstar	1998-95	34166
GM	Alero	2001-99	34236
GM	Astro	2003-96	34174
GM	Bravada	1994-91	34152
GM	C/K Series Pick-ups/Suburban	2000-96	34174
GM	C/K-Series Pick-up, Suburban, Sierra, S10 Pick-up, Tahoe, Sonoma, Yukon	1995-90	34152
GM	Cavalier, Sunfire 2.2/2.4L	2002-96	34236
GM	Grand Am	2001-96	34236
GM	Malibu	1999-97	34236
GM	S10 Blazer, Pick-up, Sonoma	1998-96	34174
GM	S10 Blazer, S15 Jimmy	1995-88	34152
GM	Skylark, Achieva 2.4L	1998-96	34236
GM	Tahoe	1998-96	34174
GM	Yukon	2000-96	34174
Isuzu	Safari	2003-96	34174
Jeep	Cherokee 2.5/4.0L	2000-96	34237
Jeep	Grand Cherokee	1998-93	34178
Jeep	Liberty 3.7L	2005-02	34238
Jeep	Wrangler 2.5/4.0L	2002-97	34237

For a complete listing of Dorman's A/C Bypass Pulleys, visit DormanProducts.com



NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES



Dorman Products, Inc.
3400 East Walnut Street | Colmar, PA 18915
Corporate Office & Customer Service: 1.800.523.2492

New Product Idea Hotline: 1-800-336-3575
www.DormanProducts.com



© 2013 No reproductions in whole or in part without prior written approval.

74620