

PLASTIC BACKED MIRROR GLASS

MARKET LEADING COVERAGE



**Covering Over 375 Million
Repair Opportunities**


**Coverage for Chrysler, Ford,
GM, Honda, Toyota more!**



Reduce Repair Cost - Replace just the broken mirror glass, not the entire mirror assembly

- A fraction of the cost of the entire assembly
- **Easy to Install** – Snap in replacements
- Repair in less than 5 minutes

MIRROR GLASS WITH INTEGRATED TURN SIGNALS



**56318 [Left]
56319 [Right]**

GM 4.3, 4.8, 5.3, 6.0, 6.6, 8.1L
2007-03



HEATED MIRROR GLASS



**56216 [Left]
56217 [Right]**
Durango 2000-99,
Ram Pickup 2002-98



NON-HEATED MIRROR GLASS



**56023 [Lower]
56024 [Upper]**
Express, Savanna, Sierra, Silverado
2010-03

PLASTIC BACKED MIRROR GLASS

APPLICATION GUIDE*

MAKE/MODEL	YEAR	TYPE	DORMAN # - LEFT -	DORMAN # - RIGHT -
CHRYSLER				
Dakota, Durango, Ram Pickup, Ram Van	2003-97	Non-Heated	56256	56257
FORD				
Expedition, Navigator	2007-03	Heated	56308	56309
F Series Pickup, Mark LT	2008-06	Non-Heated	56155	56156
GM				
Avalanche, Escalade, Sierra, Silverado, Suburban, Tahoe, Yukon	2007-99	Heated	56021	56022
Grand Prix	2008-05	Non-Heated	56027	56028
HONDA				
Civic	2005-01	Non-Heated	56339	56340
Odyssey	2009-05	Heated	56333	56334
HYUNDAI				
Elantra, Spectra	2006-01	Non-Heated	56610	56611
NISSAN				
Frontier, Pathfinder, Xterra	2010-05	Non-Heated	56522	56523
Maxima	2008-04	Heated	56500	56001
SUBARU				
Baja, Legacy	2006-00	Heated	56644	56645
TOYOTA				
Camry	2006-02	Heated	56439	56440
Corolla, Matrix	2008-02	Non-Heated	56405	56406
VOLKSWAGEN				
Jetta	2007-99	Heated	56632	56633

955-1654 [Left]
955-1655 [Right]
Avalon
2010-05



ALSO AVAILABLE:

< Complete Side Mirror Assembly
Replacements

* For Complete Plastic Backed Mirror Glass
Coverage, Visit DormanHelp.com